

Subj: **From Don Stiber**  
Date: 5/24/2005 8:02:48 AM Pacific Daylight Time  
From: DSTIBER  
To: DSTIBER  
*Right-click picture(s) to display picture options*

Paul;

I instructed my attorney to file against you today. My only question is why you did not respond so far? Instead this is going to incur attorney fees and filing cost.

Here is one final picture. Please notice that the fender is supposed to continue it line and meet the outer edge of the bumper. When the fender was reconstructed from Bondo they made the flared out part about 1/2 inch too narrow. The entire bottom of the left rear quarterpanel is a Bondo recreation. Above it there is significant hammering and filler and runs.

